

HAZARDOUS WASTE HOTLINE REPORT FORM

DATE: 8/2

10/1

TAKEN BY: _____

SITE NAME: Grind-rite Grinding and Manufacturing Co.ADDRESS: 6420 Hamlin, Lincolnwood, Ill.COUNTY: Cook

SITE DESCRIPTION: This company keeps 55-gallon drums of an oil-water mixture. Whenever it rains, there are night personnel who let it run down the company's driveway. In the employee parking lot is another place where this mixture is dumped during rainy periods, when there is so much that the parking lot surface looks like milk. It is so slick that it can cause car accidents as well. The company is moving the first of January, so the caller, who would like to remain anonymous, ask that EPA investigates the company before then. The company leads the run-off from the driveway run into the sewer.

NAME OF CALLER: _____

ADDRESS: _____

PHONE: _____

Reported to other agencies? _____

Follow-up Information Requested? _____

Immediate Action Taken: 10-14-80 Referred to Al Geidraitis, MSD. Pollution Control Officer (PCO) will be sent out + MSD will report back to me. MSD numbered it Industrial Waste Special Investigation #504.

EPA Region 5 Records Ctr.



327925